SI.No.	Location of ROB/RUB	NH	Reason thereof
1.	Chaprakata ROB at km 88.10	31-C	Delay at the part of Contractor
2.	Kalachand ROB at km 122 . 75 in NC Hills Distt	54	Contractor abandoned the work
3.	Mahur RUB at km 150.59 in NC Hills Distt	54	Contractor abandoned the work
4.	Mahur RUB at km 150.52 in NC Hills Distt	54	Contractor abandoned the work
5.	Kapurchera ROB at km 179.28 in NC Hills Distt	54	Contractor abandoned the work
5.	Redzol ROB at km 169.61 in NC Hills Distt	54	Contractor abandoned the work
7.	Harangajao RUB at km 189.30 in NC Hills Distt	54	Contractor abandoned the work
8.	Harangajao RUB at km 185.73 in NC Hills Distt	54	Contractor abandoned the work

Table 2 - Rail Over/Under Bridges yet to be started on 4-laning of East-West Corridor in Assam.

Construction of service lane alongside of toll road

†1300. SHRI LALIT KISHORE CHATURVEDI: Will the Minister of ROAD TRANSPORT AND HIGHWAYS be pleased to state:

(a) whether it will be made mandatory to construct service lane alongside each and every toll road for two wheelers, three wheelers, slow speed vehicles and animal driven carts;

(b) whether to connect the service lanes with the population over pass or under pass will be constructed on toll road so as to nullify the possibility of accidents; and

(c) whether except for lane wise, no construction will be permitted in road limit?

THE MINISTER OF STATE IN THE MINISTRY OF ROAD TRANSPORT AND HIGHWAYS (SHRI R.P.N. SINGH): (a) No, Sir.

(b) Wherever feasible, underpasses/foot over bridges are provided for crossing to other side of highway.

(c) No construction is permitted in road limits expect road appurtenances.

Improving Road Safety

1301. SHRI VIJAY JAWAHARLAL DARDA: Will the Minister of ROAD TRANSPORT AND HIGHWAYS be pleased to state:

[†]Original notice of the question was received in Hindi.