4198

MANDIRA DAM BOAT DISASTER AT

HARIHAR PATEL: *712. SHRI Will the Minister of STEEL MINES AND FUEL be pleased to state:

- (a) whether a boat carrying some passengers met with disaster Mandira Dam on or about the 11th August 1958, causing loss of many lives: and
- (b) if so, what are the details of that incident?

THE MINISTER OF STEEL, MINES AND FUEL (SARDAR SWARAN SINGH): (a) and (b). Yes, Sir.

On 12th July 1958, the Spillway channel of Mandira Dam started functioning and the area to the left side of the channel and the right side the Earth Dam got cut off from the main colony and formed an island. In order to enable the officers and workers residing in the colony to come to their worksite within the island, a temporary suspension bridge was constructed over the spillway channel some 400 feet below the channel.

On the morning of 11th August 1958 one of the supervisors noticed that an earth slip had occurred at the right abuttment supporting the temporary suspension bridge. As danger to the bridge was anticipated, traffic over the bridge was stopped at 7-30 A.M. After the authorities had visited and checked up, traffic was resumed at 7-45 A.M. During this short period when the bridge was closed to traffic, some workers had collected on the right side of the spillway. They were transported to the island by one of the two boats maintained for transporting officers and workers in case of necessity, by the Dam authorities. boats could carry about 25 persons each. While one of these boats was making its third trip with 17 persons on board, it got into the current and was crushed against the spillway crest resulting in the death of all the persons in the boat. The passengers of |

the ill fated boat consisted of 3 boatmen 10 employees, and 4 ex-employees of the Mandira Project.

The Chief Engineer immediately sanctioned, out of his discretionary fund, a sum of Rs, 100 towards funeral expenses and other charges for every bereaved family.

A court of enquiry was set up by the Chief Engineer Hirakud. court was of the view that the accident occurred as a result of negligence of the boatmen on starting the boat from a place nearer the spillway and also not plying it over the prescribed route.

COLLAPSE OF THE SUSPENSION BRIDGE NEAR MANDIRA DAM

*713. SHRI **HARIHAR** PATEL: Will the Minister of STEEL. AND FUEL be pleased to state:

- (a) whether the suspension bridgethe Mandira Dam collapsed recently; and
- (b) if so, what are the reasonstherefor?

THE MINISTER OF STEEL, MINES. AND FUEL (SARDAR SWARAN SINGH): (a) No. Sir.

(b) Does not arise.

HARIHAR PATEL: May I know. Sir, how the number of passengers in the boat has been ascertained?

MR. CHAIRMAN: 25 persons each -he said.

SARDAR SWARAN SINGH: given the number in the statement.

SHRI HARIHAR PATEL: Is there any register maintained to show the number of passengers in the boat every trip or the number is ascertained from tickets issued?

SARDAR SWARAN SINGH: There is no question of maintaining a register. We know the number of passengers and the hon. Member might recall that I have mentioned earlier that this trip.