THE MINISTER OF STATE IN THE MINISTRY OF CIVIL AVIATION (SHRI G.M. SIDDESHWARA): (a) and (b) Yes, Sir. Airports Authority of India (AAI) Board has approved recarpeting of runway and Cat-III B lighting system of Ahmedabad airport at an estimated cost of ₹ 73.64 crores. AAI has earmarked an amount of ₹ 17.92 crores in the BE 2014-15 for this work.

- (c) to (e) No, Sir. However, the Planning Commission in its Financing Plan of Airports has recommended in July, 2012 for taking up the operation and management of 6 airports including Ahmedabad Airport through Private Public Partnership model.
- (f) The PDC for work related to Cat-III B approach lighting system and recarpeting of runway is 31st March, 2016.

## Windshield cracks incidents in dreamliners

- 136. SHRI RITABRATA BANERJEE: Will the Minister of CIVIL AVIATION be pleased to state:
- (a) whether Government is aware of the series of incidents of windshield crack in the dreamliners during the last six months;
  - (b) if so, the reasons therefor; and
  - (c) what action has been taken by Government in this regard?

THE MINISTER OF STATE IN THE MINISTRY OF CIVIL AVIATION (SHRI G.M. SIDDESHWARA): (a) and (b) Yes, Sir. The on-going investigation by Boeing indicates that moisture ingress has resulted in an increased rate of occurrence. A new window design with improved features is in progress to reduce such incidents. The occurrences experienced on the airplanes were cracking of the non-structural outer glass ply, which does not affect the safety of the airplane due to the windshield's "fail safe" (multiple-layer) construction.

(c) Air India has taken up the issue with Boeing, who have informed that old windshields shall be replaced by new windshields with improved design features.

## Airport dues of Air India

- 137. SHRI VIJAY JAWAHARLAL DARDA: Will the Minister of CIVIL AVIATION be pleased to state:
- (a) whether it is a fact that the Mumbai Airport Authorities have put Air India on a cash-and-carry mode after its dues mounted to 450 crores;
  - (b) if so, the details thereof;